



United States Steel Corporation
Clairton Works
400 State Street
Clairton, PA 15025

7748-1002-000001
OR

January 8, 2014

Ms. Gail Eddings
Allegheny County Health Department
Department of Air Quality
301 Thirty-Ninth Street
Pittsburgh, PA 15201

RECEIVED
JAN 14 2014
3AP20

Subject: USS Reference Number: 14-0006
ACHD Reference Number: N/A
#1 Battery Igniter Flare
USS Clairton Works

Dear Gail Eddings,

The attached form confirms our verbal report of the subject incident and satisfies the requirements of paragraph IV.8 of the Title V operating permit #0052 as issued on March 27th 2012.

I certify that based on the information and belief formed after reasonable inquiry, the statements and information in this document are true, accurate, and complete. Any questions concerning this matter should be referred to Coleen M. Davis at 412-233-1015.

Sincerely,



Thomas E. Schumacher
Plant Manager
Clairton Works

CC: James W. Hagedorn (USEPA)

ED_002508A_00000694-00001

NOTICE OF OUTAGE OF EQUIPMENT
ARTICLE XXI - SECTION 2108.1

1. USS Reference Number: 14-0006
ACHD Reference Number: N/A
2. Date & Time of Breakdown: Date: 01/07/14 Time: 1050 hours
3. Company Name: U.S. Steel Corporation - USS Clairton Works
4. Specific Equipment Involved or Affected: #1 Battery Igniter Flare
5. BAPC Permit Number (if applicable):
6. Location: Clairton, PA
7. Nature and cause of breakdown: The #1 Battery Igniter Flared due to a frozen mercooid switch impulse line.

Date	Battery	Start Time	End Time	Duration Min. Sec.	Flared Yes	Flared No
01/07/14	1	10:50	10:55	05 00	Yes	
8. Identification of Emissions:
 - A. Type(s) (CO, NOX, SO₂, Particulates, Hydrocarbons, etc.)
Released products of combustion of Coke Oven Gas.
 - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). Eye, Nose and Throat Irritant.
 - C. Amount of each type emitted (or likely to be emitted).
Moderate.
9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).
The impulse line obstruction was cleared.
10. Facility back in operation - Date: 01/07/14 Time: 1055 hours

Reviewed by Coleen M. Davis Date 1-9-14
Coleen M. Davis
Senior Environmental Control Engineer Phone: 412-233-1015